



PIC24HJ256GPX06A/X08A/X10A Family Silicon Errata and Data Sheet Clarification

The PIC24HJ256GPX06A/X08A/X10A family devices that you have received conform functionally to the current Device Data Sheet (DS70592C), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in Table 1. The silicon issues are summarized in Table 2.

The errata described in this document will be addressed in future revisions of the PIC24HJ256GPX06A/X08A/X10A silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of Table 2 apply to the current silicon revision (A4).

Data Sheet clarifications and corrections start on page 6, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 3 or PICkit™ 3:

- 1. Using the appropriate interface, connect the device to the MPLAB ICD 3 programmer/debugger or PICkit 3.
2. From the main menu in MPLAB IDE, select Configure>Select Device, and then select the target part number in the dialog box.
3. Select the MPLAB hardware tool (Debugger>Select Tool).
4. Perform a "Connect" operation to the device (Debugger>Connect). Depending on the development tool used, the part number and Device Revision ID value appear in the Output window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The Device and Revision ID values for the various PIC24HJ256GPX06A/X08A/X10A silicon revisions are shown in Table 1.

TABLE 1: SILICON DEVREV VALUES

Table with 4 columns: Part Number, Device ID(1), and Revision ID for Silicon Revision(2) (sub-columns A2, A3, A4). Rows include PIC24HJ256GP206A, PIC24HJ256GP210A, and PIC24HJ256GP610A.

- Note 1: The Device and Revision IDs (DEVID and DEVREV) are located at the last two implemented addresses in program memory.
2: Refer to the "dsPIC33F/PIC24H Flash Programming Specification" (DS70152) for detailed information on Device and Revision IDs for your specific device.

PIC24HJ256GPX06A/X08A/X10A

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾		
				A2	A3	A4
ECAN™	WAKIF bit	1.	The WAKIF bit in the CxINTF register cannot be cleared by software instruction after the device is interrupted from Sleep due to activity on the CAN bus.	X	X	X
ECAN	DMA	2.	False DMA Error Traps may be generated in applications that perform both transmissions and receptions using ECAN with DMA.	X		
UART	Break Characters	3.	The UART module will not generate consecutive break characters.	X	X	X
ADC	DONE bit	4.	The ADC Conversion Status bit (DONE) does not work when External Interrupt is selected as the ADC trigger source.	X	X	X
SPI	TBF bit	5.	Writing to the SPIBUF register as soon as the TBF bit is cleared will cause the SPI module to ignore the written data.	X	X	X
DMA Controller	CPU Write Collision Detection	6.	DMA CPU write collisions will not be detected.		X	X
ADC	Current Consumption in Sleep Mode	7.	If the ADC module is in an enabled state when the device enters Sleep mode, the power-down current (IPD) of the device may exceed the device data sheet specifications.	X	X	X
All	150°C Operation	8.	Affected revisions of silicon only support 140°C operation instead of 150°C for extended operating temperature.	X	X	X
CPU	Interrupt Disable	9.	When a previous DISI instruction is active (i.e., the DISICNT register is non-zero), and the value of the DISICNT register is updated manually, the DISICNT register freezes and disables interrupts permanently.	X	X	X
CPU	div.sd	10.	When using the div.sd instruction, the overflow bit is not getting set when an overflow occurs.	X	X	X
UART	TX Interrupt	11.	A transmit (TX) Interrupt may occur before the data transmission is complete.	X	X	X
JTAG	Flash Programming	12.	JTAG Flash programming is not supported.	X	X	X
ADC	Analog Pins	13.	When sampling either AN0 or AN3 at 1.1 Msps on both CH0 and CH1, the CH1 sample is not identical to the CH0 sample. If CH0 and CH1 sample different ANx inputs, the samples are identical as they would be expected.	X	X	X
ECAN	DMA	14.	A DMA trap is not generated when the CPU and DMA write to the ECAN module at the same time.	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24HJ256GPX06A/X08A/X10A

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A4**).

1. Module: ECAN™

The WAKIF bit in the CxINTF register cannot be cleared by software instruction after the device is interrupted from Sleep due to activity on the CAN bus.

When the device wakes up from Sleep due to CAN bus activity, the ECAN module is placed in operational mode. The ECAN Event interrupt occurs due to the WAKIF flag. Trying to clear the flag in the Interrupt Service Routine (ISR) may not clear the flag. The WAKIF bit being set will not cause repetitive Interrupt Service Routine execution.

Work around

Although the WAKIF bit does not clear, the device Sleep and ECAN Wake functions continue to work as expected. If the ECAN event is enabled, the CPU will enter the Interrupt Service Routine due to the WAKIF flag getting set. The application can maintain a secondary flag, which tracks the device Sleep and Wake events.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

2. Module: ECAN

In user applications that perform both transmissions and receptions using ECAN with DMA, intermittent DMA Write Collisions might get generated, resulting in the generation of DMA Error Traps. The ECAN messages would be transmitted and received correctly even when these DMA Error Traps occur.

Work around

Within the DMA Error Trap service routine in the application software, read the DMACS0 register and inspect the two XWCOLn (n = 0, 1, ...,7) bits corresponding to the DMA channels being used for ECAN transmission and reception.

For example, if DMA Channel 1 is used for ECAN Reception and DMA Channel 2 is used for ECAN Transmission, inspect the XWCOL1 and XWCOL2 bits. If either of these bits is found to be set, clear the DMACERR bit in the INTCON1 register and return from the DMA Error Trap service routine.

Affected Silicon Revisions

A2	A3	A4					
X							

3. Module: UART

The UART module will not generate consecutive break characters. Trying to perform a back-to-back Break character transmission will cause the UART module to transmit the dummy character used to generate the first Break character instead of transmitting the second Break character. Break characters are generated correctly if they are followed by non-Break character transmission.

Work around

None.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

PIC24HJ256GPX06A/X08A/X10A

4. Module: ADC

The ADC Conversion Status (DONE) bit (ADxCON1<0>) does not indicate completion of conversion when External Interrupt is selected as the ADC trigger source (ADxCON1<SSRC> = 1).

Work around

Use an ADC interrupt or poll ADxIF bit in the IFSx registers to determine the completion of conversion.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

5. Module: SPI

Writing to the SPIxBUF register as soon as the TBF bit is cleared will cause the SPI module to ignore the written data. *Applications that use SPI with DMA are not affected by this erratum.*

Work around

After the TBF bit is cleared, wait for a minimum duration of one SPI clock before writing to the SPIxBUF register.

Alternatively, do one of the following:

- Poll the RBF bit and wait for it to get set before writing to the SPIxBUF register
- Poll the SPI Interrupt flag and wait for it to get set before writing to the SPIxBUF register
- Use an SPI Interrupt Service Routine
- Use DMA

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

6. Module: DMA Controller

DMA CPU write collisions will not be detected, and the corresponding XWCOLn bit (n = 0, 1, ..., 7) will not be set. As a result, a CPU write collision event will not generate a DMA Error Trap.

Work around

None. Before writing to any memory location in DMA RAM, ensure that none of the enabled DMA channels is using the same memory location for data transfers from a peripheral.

Affected Silicon Revisions

A2	A3	A4					
	X	X					

7. Module: ADC

If the ADC module is in an enabled state when the device enters Sleep mode as a result of executing a PWRSAV #0 instruction, the device power-down current (IPD) may exceed the specifications listed in the device data sheet. This may happen even if the ADC module is disabled by clearing the ADON bit prior to entering Sleep mode.

Work around

In order to remain within the IPD specifications listed in the device data sheet, the user software must completely disable the ADC module by setting the ADC Module Disable bit in the corresponding Peripheral Module Disable register (PMDx), prior to executing a PWRSAV #0 instruction.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

8. Module: All

The affected silicon revisions listed below are not warranted for operation at 150°C.

Work around

Only use the affected revisions of silicon for Hi-Temp operating range from -40°C to +140°C.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

9. Module: CPU

When a previous DISI instruction is active (i.e., the DISICNT register is non-zero), and the value of the DISICNT register is updated manually, the DISICNT register freezes and disables interrupts permanently.

Work around

Avoid updating the DISICNT register manually. Instead, use the DISI #n instruction with the required value for 'n'.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

PIC24HJ256GPX06A/X08A/X10A

10. Module: CPU

When using the Signed 32-by-16-bit Division instruction, `div.sd`, the overflow bit does not always get set when an overflow occurs.

Work around

Test for and handle overflow conditions outside of the `div.sd` instruction.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

11. Module: UART

When using `UTXISEL = 01` (Interrupt when last character is shifted out of the Transmit Shift Register) and the final character is being shifted out through the Transmit Shift Register, the Transmit (TX) Interrupt may occur before the final bit is shifted out.

Work around

If it is critical that the interrupt processing occur only when all transmit operations are complete. Hold off the interrupt routine processing by adding a loop at the beginning of the routine that polls the Transmit Shift Register Empty bit (TRMT) before processing the rest of the interrupt.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

12. Module: JTAG

JTAG Flash programming is not supported.

Work around

None.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

13. Module: ADC

When sampling either AN0 or AN3 at 1.1 Msps on both CH0 and CH1, the CH1 sample is not identical to the CH0 sample. If CH0 and CH1 sample different ANx inputs the samples are identical as they would be expected.

Work around

Bring the analog signal into the device on two separate ANx pins. This will isolate the signals to the two channels when one sample starts at the same time another sample ends.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

14. Module: ECAN

A DMA trap is not generated when the CPU and DMA write to the ECAN module transmit SFR at the same time.

Work around

The CPU should not write to the ECAN transmit SFR while the DMA is in operation.

Affected Silicon Revisions

A2	A3	A4					
X	X	X					

PIC24HJ256GPX06A/X08A/X10A

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS70592C):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: DC Characteristics: Idle Current (I_{IDLE})

The typical and maximum Idle Current specifications were incorrectly reported in Table 25-6 in the current version of the device data sheet. The correct specifications are provided in the following table.

TABLE 25-6: DC CHARACTERISTICS: IDLE CURRENT (I_{IDLE})

DC CHARACTERISTICS			Standard Operating Conditions: 3.0V to 3.6V (unless otherwise stated) Operating temperature -40°C ≤ TA ≤ +85°C for Industrial -40°C ≤ TA ≤ +125°C for Extended			
Parameter No.	Typical	Max	Units	Conditions		
Idle Current (I _{IDLE}): Core OFF Clock ON Base Current						
DC40d	11	16	mA	-40°C	3.3V	10 MIPS
DC40a	11	16	mA	+25°C		
DC40b	15	20	mA	+85°C		
DC40c	19	24	mA	+125°C		
DC41d	15	20	mA	-40°C	3.3V	16 MIPS
DC41a	15	20	mA	+25°C		
DC41b	19	24	mA	+85°C		
DC41c	24	29	mA	+125°C		
DC42d	19	24	mA	-40°C	3.3V	20 MIPS
DC42a	19	24	mA	+25°C		
DC42b	23	28	mA	+85°C		
DC42c	28	33	mA	+125°C		
DC43a	27	32	mA	+25°C	3.3V	30 MIPS
DC43d	27	32	mA	-40°C		
DC43b	30	35	mA	+85°C		
DC43c	36	41	mA	+125°C		
DC44d	35	41	mA	-40°C	3.3V	40 MIPS
DC44a	35	41	mA	+25°C		
DC44b	40	46	mA	+85°C		
DC44c	44	50	mA	+125°C		

PIC24HJ256GPX06A/X08A/X10A

2. Module: I/O Pin Output Specifications

The I/O Pin Output specifications (VOL, VOH and VOH1) were incorrectly reported in the Table 25-10 in the current version of the device data sheet. The correct specifications are provided in the following table.

TABLE 25-10: DC CHARACTERISTICS: I/O PIN OUTPUT SPECIFICATIONS

DC CHARACTERISTICS			Standard Operating Conditions: 3.0V to 3.6V (unless otherwise stated) Operating temperature -40°C ≤ TA ≤ +85°C for Industrial -40°C ≤ TA ≤ +125°C for Extended				
Param No.	Symbol	Characteristic	Min	Typ	Max	Units	Conditions
DO10	VOL	Output Low Voltage I/O Pins: 2x Sink Driver Pins - All pins not defined by 4x or 8x driver pins	—	—	0.4	V	IOL ≤ 3 mA, VDD = 3.3V See Note 1
		Output Low Voltage I/O Pins: 4x Sink Driver Pins - RA2, RA3, RA9, RA10, RA14, RA15, RB0, RB1, RB11, RF4, RF5, RG2, RG3	—	—	0.4	V	IOL ≤ 6 mA, VDD = 3.3V See Note 1
		Output Low Voltage I/O Pins: 8x Sink Driver Pins - OSC2, CLKO, RC15	—	—	0.4	V	IOL ≤ 10 mA, VDD = 3.3V See Note 1
DO20	VOH	Output High Voltage I/O Pins: 2x Source Driver Pins - All pins not defined by 4x or 8x driver pins	2.4	—	—	V	IOL ≥ -3 mA, VDD = 3.3V See Note 1
		Output High Voltage I/O Pins: 4x Source Driver Pins - RA2, RA3, RA9, RA10, RA14, RA15, RB0, RB1, RB11, RF4, RF5, RG2, RG3	2.4	—	—	V	IOL ≥ -6 mA, VDD = 3.3V See Note 1
		Output High Voltage I/O Pins: 8x Source Driver Pins - OSC2, CLKO, RC15	2.4	—	—	V	IOL ≥ -10 mA, VDD = 3.3V See Note 1

Note 1: Parameters are characterized, but not tested.

PIC24HJ256GPX06A/X08A/X10A

TABLE 25-10: DC CHARACTERISTICS: I/O PIN OUTPUT SPECIFICATIONS (CONTINUED)

DC CHARACTERISTICS			Standard Operating Conditions: 3.0V to 3.6V (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for Industrial $-40^{\circ}\text{C} \leq T_A \leq +125^{\circ}\text{C}$ for Extended				
Param No.	Symbol	Characteristic	Min	Typ	Max	Units	Conditions
DO20A	VOH1	Output High Voltage I/O Pins: 2x Source Driver Pins - All pins not defined by 4x or 8x driver pins	1.5	—	—	V	$I_{OH} \geq -6 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			2.0	—	—		$I_{OH} \geq -5 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			3.0	—	—		$I_{OH} \geq -2 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
		Output High Voltage 4x Source Driver Pins - RA2, RA3, RA9, RA10, RA14, RA15, RB0, RB1, RB11, RF4, RF5, RG2, RG3	1.5	—	—	V	$I_{OH} \geq -12 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			2.0	—	—		$I_{OH} \geq -11 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			3.0	—	—		$I_{OH} \geq -3 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
		Output High Voltage 8x Source Driver Pins - OSC2, CLKO, RC15	1.5	—	—	V	$I_{OH} \geq -16 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			2.0	—	—		$I_{OH} \geq -12 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1
			3.0	—	—		$I_{OH} \geq -4 \text{ mA}$, $V_{DD} = 3.3\text{V}$ See Note 1

Note 1: Parameters are characterized, but not tested.

PIC24HJ256GPX06A/X08A/X10A

APPENDIX A: REVISION HISTORY

Rev A Document (9/2009)

Initial release of this document; issued for revision A2 silicon.

Includes silicon issues 1-2 ([ECAN™](#)), 3 ([UART](#)), 4 ([ADC](#)) and 5 ([SPI](#)).

Rev B Document (12/2009)

Added Rev. A3 silicon information.

Added silicon issue 6 ([DMA Controller](#)).

Rev C Document (6/2010)

Added silicon issue 7 ([ADC](#)) and data sheet clarification 1 (DC Characteristics: I/O Pin Input Specifications).

Rev D Document (9/2010)

Added silicon issue 8 ([All](#)).

Rev E Document (3/2011)

Removed data sheet clarification 1.

Rev F Document (11/2011)

Added silicon issues 9 ([CPU](#)), 10 ([CPU](#)), 11 ([UART](#)), and 12 ([JTAG](#)).

Rev G Document (4/2012)

Added Rev. A4 silicon information.

Added silicon issues 13 ([ADC](#)) and 14 ([ECAN](#)) and data sheet clarifications 1 ([DC Characteristics: Idle Current \(IDLE\)](#)) and 2 ([I/O Pin Output Specifications](#)).

PIC24HJ256GPX06A/X08A/X10A

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICKit, PICtail, REAL ICE, rLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2009-2012, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 978-1-62076-179-3

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
= ISO/TS 16949 =**

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC[®] MCUs and dsPIC[®] DSCs, KEELOQ[®] code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Cleveland
Independence, OH
Tel: 216-447-0464
Fax: 216-447-0643

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara
Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office
Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8569-7000
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Chongqing
Tel: 86-23-8980-9588
Fax: 86-23-8980-9500

China - Hangzhou
Tel: 86-571-2819-3187
Fax: 86-571-2819-3189

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing
Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Xiamen
Tel: 86-592-2388138
Fax: 86-592-2388130

China - Zhuhai
Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444
Fax: 91-80-3090-4123

India - New Delhi
Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Osaka
Tel: 81-66-152-7160
Fax: 81-66-152-9310

Japan - Yokohama
Tel: 81-45-471-6166
Fax: 81-45-471-6122

Korea - Daegu
Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur
Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang
Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-5778-366
Fax: 886-3-5770-955

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-330-9305

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820

11/29/11